(The information in this table indicates the dominant soil condition but does not eliminate the need for onsite investigation. The numbers in the value columns range from 0.01 to 1.00. The larger the value, the greater the limitation. See text for further explanation of ratings in this table.)

Map symbol and soil name	Pct. of map unit	Septic tank absorption fields		Sewage lagoons	
		Rating class and limiting features	Value	Rating class and limiting features	Value
1B3: Ida	100	Not limited restricted permeability	0.25	Somewhat limited Seepage	0.50
1C3: Ida	95	Not limited restricted permeability	0.25	Very limited Slope Seepage	1.00
1D3: Ida	95	Somewhat limited Slope restricted permeability	0.63	Very limited Slope Seepage	1.00
1E3: Ida	95	Very limited Slope restricted permeability	1.00	Very limited Slope Seepage	1.00
1F3: Ida	95	Very limited Slope restricted permeability	1.00	Very limited Slope Seepage	1.00
1G3: Ida	95	Very limited Slope restricted permeability	1.00	Very limited Slope Seepage	1.00
2G: Hamburg	95	Very limited Slope restricted permeability	1.00	Very limited Slope Seepage	1.00

(The information in this table indicates the dominant soil condition but does not eliminate the need for onsite investigation. The numbers in the value columns range from 0.01 to 1.00. The larger the value, the greater the limitation. See text for further explanation of ratings in this table.)

Plymouth County, Iowa

Map symbol and soil name	Pct. of map unit	Septic tank absorption fields		Sewage lagoons	
		Rating class and limiting features	Value	Rating class and limiting features	Value
3F: Castana	95	Very limited Slope restricted permeability	1.00	Very limited Slope Seepage	1.00
10B: Monona	95	Not limited restricted permeability	0.25	Somewhat limited Seepage Slope	0.50
10C2: Monona	90	Not limited restricted permeability	0.25	Very limited Slope Seepage	1.00
10D2: Monona	90	Somewhat limited Slope restricted permeability	0.63	Very limited Slope Seepage	1.00
10E2: Monona	90	Very limited Slope restricted permeability	1.00	Very limited Slope Seepage	1.00
12C: Napier	95	Not limited restricted permeability	0.25	Very limited Slope Seepage	1.00
14D: Castana	95	Somewhat limited Slope restricted permeability	0.63	Very limited Slope Seepage	1.00

USDA-NRCS, IOWA

(The information in this table indicates the dominant soil condition but does not eliminate the need for onsite investigation. The numbers in the value columns range from 0.01 to 1.00. The larger the value, the greater the limitation. See text for further explanation of ratings in this table.)

Plymouth County, Iowa

Map symbol and soil name	Pct. of map unit	Septic tank absorption fields		Sewage lagoons	
		Rating class and limiting features	Value	Rating class and limiting features	Value
18B: Mcpaul	50	Very limited Flooding Depth to saturated zone restricted permeability	1.00	Very limited Flooding Slope	1.00
Kennebec	30	Very limited Flooding Depth to saturated zone restricted permeability	1.00 1.00 0.25	Very limited Flooding Depth to saturated zone Seepage Slope	1.00 0.71 0.50 0.33
19B: Kennebec	50	Very limited Flooding Depth to saturated zone restricted permeability	1.00	Very limited Flooding Depth to saturated zone Seepage Slope	1.00 0.71 0.50 0.33
Mcpaul	30	Very limited Flooding Depth to saturated zone restricted permeability	1.00	Very limited Flooding Slope	1.00
26: Kennebec	95	Very limited Flooding Depth to saturated zone restricted permeability	1.00	Very limited Flooding Depth to saturated zone Seepage	1.00 0.71 0.50
28B: Dickman	95	Very limited Filtering capacity	1.00	Very limited Seepage Slope	1.00

USDA-NRCS, IOWA

(The information in this table indicates the dominant soil condition but does not eliminate the need for onsite investigation. The numbers in the value columns range from 0.01 to 1.00. The larger the value, the greater the limitation. See text for further explanation of ratings in this table.)

Map symbol and soil name	Pct. of map unit	absorption fields		Sewage lagoons	
		Rating class and limiting features	Value	Rating class and limiting features	Value
33D3: Steinauer	95	Somewhat limited Restricted permeability Slope	0.91	Very limited Slope	1.00
33E3: Steinauer	95	Very limited Slope Restricted permeability	1.00	Very limited Slope	1.00
33F3: Steinauer	95	Very limited Slope Restricted permeability	1.00	Very limited Slope	1.00
36: Salix	95	Somewhat limited Depth to saturated zone restricted permeability	0.40	Somewhat limited Seepage	0.50
66: Luton	95	Very limited Flooding Depth to saturated zone Restricted permeability	1.00	Very limited Flooding Depth to saturated zone	1.00
70: Mcpaul	95	Very limited Flooding Depth to saturated zone restricted permeability	1.00	Very limited Flooding	1.00

(The information in this table indicates the dominant soil condition but does not eliminate the need for onsite investigation. The numbers in the value columns range from 0.01 to 1.00. The larger the value, the greater the limitation. See text for further explanation of ratings in this table.)

Plymouth County, Iowa

Map symbol and soil name	Pct. of map unit	Septic tank absorption fiel	ds	Sewage lagoons	
		Rating class and limiting features	Value	Rating class and limiting features	Value
91B: Primghar	95	Very limited Depth to saturated zone restricted permeability	1.00	Somewhat limited Depth to saturated zone Seepage Slope	0.71
108B: Wadena	95	Very limited Filtering capacity restricted permeability	1.00	Very limited Seepage Slope	1.00
114D3: Ida	50	Not limited restricted permeability Slope	0.25	Very limited Slope Seepage	1.00
Wadena	30	Very limited Filtering capacity restricted permeability Slope	1.00 0.25 0.16	Very limited Seepage Slope	1.00
116: Graceville	90	Very limited Filtering capacity Depth to saturated zone restricted permeability	1.00 0.43 0.25	Very limited Seepage	1.00
116B: Graceville	90	Very limited Filtering capacity Depth to saturated zone restricted permeability	1.00 0.43 0.25	Very limited Seepage Slope	1.00

USDA-NRCS, IOWA

04/30/2002

(The information in this table indicates the dominant soil condition but does not eliminate the need for onsite investigation. The numbers in the value columns range from 0.01 to 1.00. The larger the value, the greater the limitation. See text for further explanation of ratings in this table.)

Map symbol and soil name	Pct. of map unit	Septic tank absorption fields		Sewage lagoons	
		Rating class and limiting features	Value	Rating class and limiting features	Value
133: Colo	95	Very limited Flooding Depth to saturated zone restricted permeability	1.00 1.00 0.25	Very limited Flooding Depth to saturated zone Seepage	1.00
133+: Colo	100	Very limited Flooding Depth to saturated zone restricted permeability	1.00 1.00 0.25	Very limited Flooding Depth to saturated zone Seepage	1.00 1.00 0.50
149: Modale Variant	95	Very limited Flooding Depth to saturated zone Restricted permeability	1.00	Very limited Flooding Depth to saturated zone	1.00
156: Albaton	95	Very limited Depth to saturated zone Restricted permeability Flooding	1.00 1.00 0.40	Very limited Depth to saturated zone Flooding	1.00
170D: Napier	50	Somewhat limited Slope restricted permeability	0.63	Very limited Slope Seepage	1.00
Castana	30	Somewhat limited Slope restricted permeability	0.63	Very limited Slope Seepage	1.00

(The information in this table indicates the dominant soil condition but does not eliminate the need for onsite investigation. The numbers in the value columns range from 0.01 to 1.00. The larger the value, the greater the limitation. See text for further explanation of ratings in this table.)

Map symbol and soil name	Pct. of map unit	absorption fields		Sewage lagoons	
		Rating class and limiting features	Value	Rating class and limiting features	Value
189: Omadi	95	Very limited Flooding Depth to saturated zone restricted permeability	1.00	Very limited Flooding Seepage	1.00
212: Kennebec	95	Very limited Flooding Depth to saturated zone restricted permeability	1.00 1.00 0.25	Very limited Flooding Depth to saturated zone Seepage	1.00 0.71 0.50
212B: Kennebec	95	Very limited Flooding Depth to saturated zone restricted permeability	1.00 1.00 0.25	Very limited Flooding Depth to saturated zone Seepage Slope	1.00 0.71 0.50 0.33
310B: Galva	95	Not limited restricted permeability	0.25	Somewhat limited Seepage Slope	0.50
310C2: Galva	85	Not limited restricted permeability	0.25	Very limited Slope Seepage	1.00
310D2: Galva	90	Somewhat limited Slope restricted permeability	0.63	Very limited Slope Seepage	1.00

(The information in this table indicates the dominant soil condition but does not eliminate the need for onsite investigation. The numbers in the value columns range from 0.01 to 1.00. The larger the value, the greater the limitation. See text for further explanation of ratings in this table.)

Map symbol and soil name	Pct. of map unit	Septic tank Sewage absorption fields		Sewage lagoons	lagoons	
		Rating class and limiting features	Value	Rating class and limiting features	Value	
317C2: Galva	50	Not limited restricted permeability Slope	0.25	Very limited Slope Seepage	1.00	
Wadena	30	Very limited Filtering capacity restricted permeability Slope	1.00 0.25 0.16	Very limited Seepage Slope	1.00	
378: Rough Broken Land	100	Not rated		Not rated		
467: Radford	95	Very limited Flooding Depth to saturated zone restricted permeability	1.00 1.00 0.25	Very limited Flooding Depth to saturated zone Seepage	1.00	
467B: Radford	90	Very limited Flooding Depth to saturated zone restricted permeability	1.00	Very limited Flooding Depth to saturated zone Seepage Slope	1.00 1.00 0.50 0.33	
478: Steep Rock Land	95	Not rated		Not rated		

(The information in this table indicates the dominant soil condition but does not eliminate the need for onsite investigation. The numbers in the value columns range from 0.01 to 1.00. The larger the value, the greater the limitation. See text for further explanation of ratings in this table.)

Map symbol and soil name	Pct. of map unit	Septic tank absorption field	ds	Sewage lagoons	
		Rating class and limiting features	Value	Rating class and limiting features	Value
607: Salix Variant	95	Somewhat limited Depth to saturated zone Flooding restricted permeability	0.40	Somewhat limited Seepage Flooding	0.50
609: Omadi	50	Very limited Flooding Depth to saturated zone restricted permeability	1.00 0.40 0.25	Very limited Flooding Seepage	1.00
Alluvial Land	30	Not rated		Not rated	
717C: Napier		Not limited restricted permeability	0.25	Very limited Slope Seepage	0.91
Gullied Land	30	Not rated		Not rated	
733: Calco	95	Very limited Flooding Depth to saturated zone restricted permeability	1.00 1.00 0.25	Very limited Flooding Depth to saturated zone Seepage	1.00
983D: Castana	50	Somewhat limited Slope restricted permeability	0.63	Very limited Slope Seepage	1.00

(The information in this table indicates the dominant soil condition but does not eliminate the need for onsite investigation. The numbers in the value columns range from 0.01 to 1.00. The larger the value, the greater the limitation. See text for further explanation of ratings in this table.)

Plymouth County, Iowa

Map symbol and soil name	Pct. of map unit	absorption fields		Sewage lagoons	
		Rating class and limiting features	Value	Rating class and limiting features	Value
Gullied Land	30	Not rated		Not rated	
C212: Kennebec	90	Very limited Flooding Depth to saturated zone restricted permeability	1.00	Very limited Flooding Depth to saturated zone Seepage	1.00 0.71 0.50
T10B: Monona	95	Not limited restricted permeability	0.25	Somewhat limited Seepage Slope	0.50
T310: Galva	95	Not limited restricted permeability	0.25	Somewhat limited Seepage	0.50
T310B: Galva	95	Not limited restricted permeability	0.25	Somewhat limited Seepage Slope	0.50

USDA-NRCS, IOWA